

Report ID: 25,532,283 Version: 2 20 Feb 2024 Created:

Make:	MG	Model:	ZS	Body Style:	SUV		Pass	Fail	N/A	
Year:	2023	Registration:	PWD524	Reg Expiry:	28 Mar 2024	Engine	1	1	I	
WoF Expiry:		Odometer:	9,403 Kms	Good No:	25532283	Oil level	~			
VIN:	LSJW74U93NZ243468	Next Service:	10,000 kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		с I II	<b>D</b>		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:		-0	S S			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- Alle			1n-	EIU -	Operation	~			
R = rust				10	THIA	Noise	~			
PT = paint def C = crack				+		Clutch	~		~	
P = pin dent	Ho					CV joints	~		~	
* = decals	D AIR			AL-		Wheel bearings	~			
SC = stone chips							Brakes			
W = significant scuffs						Performance				
		Noto: con	Ledefects & blemishes			Hand Brake	~			
Body Insp	pection Comments	Note. son	le délects & biennisnes	indy not be disp	hayed in the diagram			~ <b>f t</b>		
						Tyres (lowest observed tread depth of tyres)				
						Left front		.5	mm	
						Right front		.5	mm	
[						Left rear		.0	mm	
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
						Suspension				
Fwd						Suspension performance	~			
						Steering performance	~			
	Shock absorbers	~								
						Air Conditioning / Heater	1			
Interior Comments						Operation 🖌				
Good						Electrical / Accessories				
Seats	dood					Head lights	~			
Carpets	Good					Tail lights	~			
	Caral					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
Dastibua						Window winder FL	~			
	•					Window winder FR	~			
General Comments Boot parcel tray split,						Window winder RL	~			
Boot parcel	tray split,					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
,						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Marlon Espena Date: 19 Jan 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....