

Report ID: 25,541,420 Version: 3 14 Jun 2024 Created:

Make: Honda Model: Vezel Body Style: H	latchback	Pass	Fail	N/A	
	0 Feb 2024 Engine		-		
	5541420 Oil level	~			
VIN: 7AT08GDHX2102349C Next Service: 97600 Service History:	No Smoke & fumes	~			
	Performance	~			
Note: This report is not a warranty	Neire	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not be diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Ve	een dismantied or	•			
a full mechanical inspection prior to purchase and this can be arranged for an additional ch		~			
	Performance	~			
Key: S SP SP	Radiator / Hoses (visual)	~			
S = scratch	Transmission	•			
D = dent	S Operation	~			
R = rust PT = paint defect	Noise	~			
C = crack	SC Clutch	•		~	
P = pin dent	CV joints	~		•	
*=decals SC QQ	S Wheel bearings	~			
SC = stone chips	Brakes	•			
W = significant scuffs	S P Performance	~			
Note: some defects & blemishes may not be displa		~			
Body Inspection Comments	Tyres (lowest observed treat		of tyre	es)	
	Left front	7.0 mm			
	Right front	7.	-	mm	
	Left rear	7.		mm	
Conditions During Body Inspection:	Right rear	7.		mm	
	Spare	7.	N/A		
Under Carriage & Under Bonnet Inspection Comments		Suspension			
	Suspension performance	~			
	Steering performance	~			
	Shock absorbers	~			
	Air Conditioning / Heater	-			
	Operation	~			
Interior Comments	Electrical / Accessories	•			
Seats Good	Head lights	~			
Good	Tail lights	~			
Carpets	Indicators	~			
Panels Good	Dashboard warning lights	~			
	Wipers (front & rear)	~			
Dashboard	Window winder FL	~			
	Window winder FR	~			
General Comments	Window winder RL	~			
-	Window winder RR	~			
	Rear view mirrors	~			
	Radio (basic test only)	~			
	CD (basic test only)			~	
	Number of keys	2		I	
Road Conditions During Test Drive: Dry	Central locking	~			
	Remote locking	~			
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera	~			
Inspected by: Lukin Koveskali Date: 25 Jan 2024					

I have read and understood this condition guide.

Name: .....

Signature: .....