

Basic Vehicle Condition Guide

Service History:

Report ID: 25,541,483

Version: 1

Created: 13 Mar 2024

Make:ToyotaModel:NoahBody Style:Year:2014Registration:Reg Expiry:WoF Expiry:12 Mar 2025Odometer:120,588 KmsGood No:25541483


Next Service:

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

130,500kms



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive.

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Rear gate panel cracked.		
Dashboard	Good		

General Comments

Foot parking brake.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Takaya Murayama Date: 13 Mar 2024

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<i>V</i>			
Radiator / Hoses (visual)	~			
Transmission	ı			
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front		5	mm	
Right front		5	mm	
Left rear		5	mm	
Right rear	5		mm	
Spare		N/A		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	V			
Wipers (front & rear)	<i>'</i>			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	3			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

I have read and understood this condition guide.

Name:

Signature: