

Basic Vehicle Condition Guide

Report ID: 25,543,391


Version: 4

Created: 14 Mar 2024

Make: Model: Toyota Hiace **Body Style:** Van Year: 2014 Registration: HRE189 Reg Expiry: 24 Sep 2024 WoF Expiry: **Odometer: Good No:** 21 Dec 2023 16,799 Kms 25543391 VIN: **Next Service:** JTFPT22P000013270 27000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rwd

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Inspected by:

One remote key not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

D 1 20 les 202

	Pass	Fail	N/A
Engine			•
Oil level	~		
Smoke & fumes	~		
Performance	V V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	'		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	!s)
Left front	7.		mm
Right front	5.		mm
Left rear		.0	mm
Right rear	6		mm
Spare	-	Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	./		
Tail lights	•		
Indicators	•		
Dashboard warning lights	./		
Wipers (front & rear)			
Window winder FL	\(\times \) \(\t		
Window winder FR			
	~		
Window winder RL			•
Window winder RR			•
Rear view mirrors	•		
Radio (basic test only)	•		
CD (basic test only)	~		
Number of keys	2		
Central locking	-		
Remote locking	-		
Sat. Nav. (basic test only)			~
Reversing camera			
Date: 30 Jan 202	24		

I have read and understood this condition guide.

Marlon Espena

Name			