

Basic Vehicle Condition Guide

Report ID: 25,550,839


Version: 1

Created: 01 Feb 2024

Make: Model: Mercedes-Benz A-Class **Body Style:** Hatchback Year: 2005 Registration: GJT244 Reg Expiry: 30 Nov 2023 WoF Expiry: **Odometer:** 27 Jun 2024 189,281 Kms **Good No:** 25550839 VIN: WDD1690072J159438 **Next Service:** overdue Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlights faded. Windscreen has stonechips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks. Both outer cv leaking grease. Lh outer cv split. Coolant bottle has cracks. Oil level half. Oil dirty

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

Dash screen dim. A/c working during inspection. 12v accessories socket cap broken.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

31 Jan 2024 Inspected by: Reuben Harvey Date:

Name:

| | Pass | Fail | N/A |
|-----------------------------|------------|---------|---------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | • |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | ! | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ' | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed trea | d depth | of tyre | es) |
| Left front | 6 | .5 | mm |
| Right front | 3.5 | | mm |
| Left rear | 3 | .5 | mm |
| Right rear | 3.5 | | mm |
| Spare | | Yes | |
| Suspension | 1 | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | 1 | | |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | V V | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | V | | |
| Number of keys | 1 | | |
| Central locking | · | | |
| Remote locking | \ <u>'</u> | | |
| Sat. Nav. (basic test only) | + | | V |
| Reversing camera | | | ~ |
| I | 1 | 1 | 1 - |

Signature: