

Report ID: 25,554,456 Version: 3 10 Apr 2024 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2019	<b>Registration:</b>	MKU967	Reg Expiry:	22 Mar 2024	Engine			
WoF Expiry:		Odometer:	97,195 Kms	Good No:	25554456	Oil level	~		
VIN:	JTNK43BEX03071529	Next Service:	101,754	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Noise	~		
						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	S R SC		S R SC S P		S	Performance	~		
Key: S H SC   S = scratch   D = dent   R = rust   PT = paint defect   C = crack						Radiator / Hoses (visual)	~		
						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S R SC S R P S D						Performance	~		
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Minor stone chips in windscreen						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Minor stone chips in windscreen						Left front 4.0 m			
						Right front	4		mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at worn				Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General Comments						Window winder RL	~		
Drives well						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Samuel Weir Date: 08 Feb 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....