

Basic Vehicle Condition Guide

Report ID: 25,559,793


Version: 2

Created: 10 May 2024

Make: Model: Mazda Atenza **Body Style:** Hatchback Year: 2010 Registration: LDY123 Reg Expiry: 22 Sep 2024 **Odometer:** WoF Expiry: 04 Dec 2024 211,435 Kms **Good No:** 25559793 VIN: 7AT0C139X17200866 **Next Service:** overdue Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlights faded. Windscreen has stonechips. Lh front fog light assembly loose

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average. top of dash peeling		

General Comments

A/c working during inspection. Sun glasses holder broken.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

08 Feb 2024 Inspected by: Reuben Harvey

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	V V			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<i>v</i>			
Radiator / Hoses (visual)	~			
Transmission		1		
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		ı		
Performance	~			
Hand Brake	~			
Tyres (lowest observed treac	d depth	of tyre	es) 	
Left front	3	.5	mm	
Right front	3.5		mm	
Left rear	7.0		mm	
Right rear	7.0		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories	I	I		
Head lights	•			
Tail lights	/			
Indicators	<i>V</i>			
Dashboard warning lights	•			
Wipers (front & rear)	•			
Window winder FL	V V V			
Window winder FR	•			
Window winder RL	v			
Window winder RR				
Rear view mirrors	V		-	
Radio (basic test only)	<i>'</i>		.,	
CD (basic test only)	1			
Number of keys	1			
Central locking	•			
Remote locking				
Sat. Nav. (basic test only) Reversing camera			1	
neversing carriera				

I have read and understood this condition guide.

Name:

Signature: