

Basic Vehicle Condition Guide

Report ID: 25,559,985


Version: 2

Created: 22 Feb 2024

Make: Model: Nissan Tiida **Body Style:** Sedan Year: 2009 Registration: LEY101 Reg Expiry: 10 Feb 2024 WoF Expiry: **Odometer:** 07 Mar 2025 124,977 Kms **Good No:** 25559985 VIN: 7AT0DH78X18208635 Next Service: 135000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

| Conditions During | Body Inspection: |
|--------------------------|------------------|
|--------------------------|------------------|

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | <u>S</u> |
|-------------------|----------|
| Seats | Average |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

General Comments

Servicing receipts in glovebox

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lukin Koveskali 13 Feb 2024 Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|---|-----------------|------|---------------------------------------|
| Engine Oil level | | | 1 |
| Smoke & fumes | • | | |
| | <i>v</i> | | |
| Performance | • | | |
| Noise | • | | |
| Cooling System | | | 1 |
| Coolant condition | \(\triangle \) | | |
| Performance | • | | |
| Radiator / Hoses (visual) | • | | |
| Transmission | Ι. | | 1 |
| Operation | • | | |
| Noise | - | | |
| Clutch | _ | | · |
| CV joints | - | | |
| Wheel bearings | <i>'</i> | | |
| Brakes | | | 1 |
| Performance | ~ | | |
| Hand Brake | <i>'</i> | | <u> </u> |
| Tyres (lowest observed tread | | | _ |
| Left front | | 7 | mm |
| Right front | | 7 | mm |
| Left rear | | 5 | mm |
| Right rear | | 5 | mm |
| Spare | | Yes | |
| Suspension | | | 1 |
| Suspension performance Steering performance | ~ | | |
| Shock absorbers | • | | |
| | • | | |
| Air Conditioning / Heater | | | |
| Operation Electrical / Accessories | <i>-</i> | | |
| Head lights | | | Ι |
| Tail lights | | | |
| Indicators | • | | |
| Dashboard warning lights | 1/ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | 1/ | | |
| Window winder FR | \(\times \) | | |
| Window winder RL | 1/ | | |
| Window winder RR | <i>y</i> | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | 1 |
| Number of keys | 1 | | _ |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | <u> </u> | | _ |
| Reversing camera | | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| g camera | | | |

Signature: