

Basic Vehicle Condition Guide

Report ID: 25,562,318


Version: 1

Created: 22 Feb 2024

Make: Model: Renault Captur **Body Style:** SUV Year: 2019 Registration: LZL7 Reg Expiry: 25 Sep 2024 WoF Expiry: **Odometer: Good No:** 05 Mar 2025 54,554 Kms 25562318 VIN: VF12R141A60843003 Next Service: 79000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

15 Feb 2024 Inspected by: Greg Morgan

| | Pass | Fail | N/A | |
|--|---|------|----------|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | .0 | mm | |
| Right front | | | mm | |
| Left rear | | .0 | mm | |
| Right rear | 4.0 | | mm | |
| Spare | • | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | <i>'</i> | | | |
| Air Conditioning / Heater | | | | |
| Operation | ·/ | | | |
| Electrical / Accessories | | | | |
| Head lights | v | | | |
| Tail lights | | | | |
| Indicators | ./ | | | |
| | VVV | | | |
| Dashboard warning lights Wipers (front & rear) | | | | |
| Window winder FL | | | | |
| | ' | | | |
| Window winder FR | V | | | |
| Window winder RL | V | | | |
| Window winder RR | V | | | |
| Rear view mirrors | | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ' | |
| Number of keys | 2 | | 1 | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| Reversing camera | ~ | | | |
| Date: 15 Feb 2024 | | | | |

I have read and understood this condition guide.

Name:

Signature: