

Report ID: 25,565,937 Version: 1 02 Apr 2024 Created:

Make:	Nissan	Model:	Fuga	Body Style: Sedan]	Pass Fa	ail N/A
Year:	2013	Registration:	rugu	Reg Expiry:	Engine	1 435	
WoF Expiry:		Odometer:	82,304 Kms	Good No: 25565937	Oil level	~	
VIN:	7AT0DH8GX24501499			Service History: No	Smoke & fumes		
	78100180824301495	Heat Service.	92,302 KIII3		Performance		
	port is not a warranty					~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Noise		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.					Cooling System		
					Coolant condition	~	
Key:					Performance	~	
S = scratch	R	(0)		100	Radiator / Hoses (visual)	~	
					Transmission		
R = rust					Operation	~	
PT = paint def	ect N				Noise	~	
C = crack					Clutch		~
P = pin dent * = decals SC DDD					CV joints	~	
SC = stone chips					Wheel bearings	~	
W = significant scuffs					Brakes		
		\sim	Р		Performance	~	
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be displayed in the diagram	Hand Brake	~	
					Tyres (lowest observed tread depth of tyres)		
					Left front	6.9	mm
					Right front	6.9	mm
					Left rear	6.9	mm
Conditions During Body Inspection: Dry					Right rear	6.9	mm
					Spare	Y	es
Under Carriage & Under Bonnet Inspection Comments					Suspension		
					Suspension performance	~	
					Steering performance	~	
					Shock absorbers	~	
					Air Conditioning / Heater		1
					_ Operation	v	
Interior Comments					Electrical / Accessories	-	
Seats	Good				Head lights	~	
					Tail lights	v	
Carpets	Good				Indicators	~	
Danala	Good				Dashboard warning lights	~	
Panels					Wipers (front & rear)	v v	
Dashboa	rd Good				Window winder FL	v v	
					Window winder FL		
General (<u>Comments</u>				Window winder FR		_
					Window winder RR	~	
					Rear view mirrors		
					Radio (basic test only)		
		CD (basic test only)	/				
					Number of keys	2	
Road Conditions During Test Drive: Dry							
Engine	ning Machanism	Timine	Chain		Remote locking	~	
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:							~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:	Reversing camera	~	
Inspected by: Hoani Saunders Date: 02 Apr 2024							

I have read and understood this condition guide.

Name:

Signature: