


<b>Make:</b>	Hyundai	<b>Model:</b>	Iload	<b>Body Style:</b>	Van
<b>Year:</b>	2020	<b>Registration:</b>	MRN646	<b>Reg Expiry:</b>	27 Apr 2024
<b>WoF Expiry:</b>	11 Apr 2025	<b>Odometer:</b>	122,222 Kms	<b>Good No:</b>	25567594
<b>VIN:</b>	KMFWBX7KMLU10105	<b>Next Service:</b>	131,000 Kms	<b>Service History:</b>	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Boot lid window tint is cut  
Front right door sill seal is torn  
Rear emblem missing from boot lid  
Holes drilled in to boot lid door jamb and dent in boot lid door jamb

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Engine and transmission oil seepage  
Chassis slightly bent behind rear bumper on left side

**Interior Comments**

Seats	Good
Carpets	Wear on drivers side
Panels	Good
Dashboard	Good

**General Comments**

Brake pedal rubber is worn

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.0	mm	
Right front	6.0	mm	
Left rear	5.0	mm	
Right rear	6.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Hoani Saunders

Date: 18 Apr 2024

I have read and understood this condition guide. Name: ..... Signature: .....