

Basic Vehicle Condition Guide

Report ID: 25,569,308


Version: 1

Created: 27 Feb 2024

Make: Model: Mercedes-Benz C250 **Body Style:** Wagon Year: 2015 Registration: PBF703 Reg Expiry: 02 Aug 2024 WoF Expiry: **Odometer:** 140,000 Kms **Good No:** 25569308 VIN: WDD2052452F18313(Next Service: 134,894kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil weep between engine & gearbox area. Inner edge on both rear tyres are worn very low, both rear tyres are very low on tread depth, will need replaced soon.

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Correct kms are 134,789kms.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young

Pass	Fail	N/A
~		
~		
~		
V		
V		
·		
~		
~		
~		
		•/
4		
•		
•		
l dopth	of tur)
		mm
		•
		mm
		mm
		mm
	N/A	
•		
•		
•		
_		
<i>\</i>		
~		
/		
/		
/		
/		
✓ ✓		
~		
V		
ン ン ン		
\(\times \)		
✓✓✓✓1		
✓✓✓✓1		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	

I have read and understood this condition guide.

Name:

Signature: