

Report ID: 150 Version: 3

06 May 2024 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	MEU68	Reg Expiry:	10 Dec 2024	Engine	1	1	
WoF Expiry:	16 Aug 2024	Odometer:	109,500 Kms	Good No:	25570245	Oil level			~
VIN:	7AT0DH8KX19121109	Next Service:		Service Histor	y:	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S S	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s dla			715	HILS	Operation	~		
R = rust PT = paint defe				$\left( \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals				- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P S S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	•	oftvre	<u> </u>
						Left front 3.5 m			
						Right front		.9 .0	mm
						Left rear		.0	mm
Conditions Duving Rody Inspection, D.						Right rear			mm
Conditions During Body Inspection: Dry						Right rear 4.0 mm   Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	UST ON SUBFRAME	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation V			
Interior Comments						Electrical / Accessories			
Seats AVERAGE						Head lights	~		
Jeals						Tail lights	~		
Carpets	AVERAGE						~		<sup> </sup>
Denele	AVERAGE					Dashboard warning lights	~		
Panels						Wipers (front & rear)	v v		
Dashboa	rd AVERAGE					Window winder FL	v v		<sup> </sup>
					]	Window winder FE	v v		<sup> </sup>
General C	<u>Comments</u>					Window winder RL	v v		<sup> </sup>
owner states this vehicle fully charged can do 120kms						Window winder RL Window winder RR	<i>v</i> <i>v</i>		<sup> </sup>
						Rear view mirrors	<i>v</i> <i>v</i>		<sup> </sup>
						Radio (basic test only)	<i>v</i> <i>v</i>		<sup> </sup>
						CD (basic test only)			
						Number of keys	2		~
Dead Conditions During Test Driver 2						Central locking	2 ✓		
Road Conditions During Test Drive: Dry						Remote locking	-		<sup> </sup>
Engine Timing Mechanism: Timing Chain							~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		- ···· IV				Reversing camera	~		
Inspected	d by: Sunny					Date: 14 Feb 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....