

Report ID: 25,572,120 Version: 2 05 May 2024 Created:

Make:	Mazda	Model:	Axela	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2005	Registration:	HKD271	Reg Expiry:	07 Apr 2024	Engine	1	I		
WoF Expiry:		Odometer:	248,605 Kms	Good No:	25572120	Oil level	~			
VIN:	7AT0C13JX14211108	Next Service:	0	Service Histor	y: No	Smoke & fumes	V			
			-		-	Performance	~			
	port is not a warranty		с I I			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	• •			
Key:	SC W	-0	SDW SD		S D SC W	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	sscw 6			The	BID SDC	Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint defe C = crack	ect M			+	SC W	Clutch	V			
P = pin dent	Ht				JIII —		~		~	
* = decals	scw PR			AL-	ELIP SW	CV joints				
SC = stone chips						Wheel bearings Brakes	5			
W = significant scuffs SC W S P SC W P SC W S P SC W									I	
		Noterer				Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	 I al a statistica 	- (-		
						Tyres (lowest observed tread depth of tyres)			-	
						Left front		.0	mm	
						Right front	1.0 m		mm	
						Left rear	2.0 mr		mm	
Conditions During Body Inspection: Dry						Right rear	2.0 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
·						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation		~		
Interior Comments						Electrical / Accessories				
Seats	wear,worr	n,minor stains ,				Head lights	~			
Comoto	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	ignition ba	arrel needs atten	tion ,			Dashboard warning lights		~		
	ignition ke	ey broken away fr	om pad needs fixing,			Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
Drives okay	ignition key needs fixi,	ng broken ,need	s a service ,engine che	ck light is on,		Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry Central locking										
						Remote locking	~	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
<u> </u>										
Inspected by: Donovan Matara Date: 12 Feb 2024										

I have read and understood this condition guide.

Name:

Signature: