

Report ID: 25,572,675 Version: 7 24 Apr 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	Registration:	JYE781	Reg Expiry:	01 Jun 2024	Engine	1		1
WoF Expiry:	28 Feb 2025	Odometer:	137,422 Kms	Good No:	25572675	Oil level	~		1
VIN:	MMU148LK0GH63030	Next Service:	147000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		+
						Performance	~		
	port is not a warranty a guide only. Conside	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		+
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/ł	n from cold. The '	Vendor recommends	Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:		-0	S S	-161-	s	Radiator / Hoses (visual)	~		+
S = scratch	RE	A U			The second	Transmission	•		<u> </u>
D = dent				The	EID S	Operation	~		1
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints			~
* = decals	- PIK			AL	EIPERS	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs S D S D S D						Performance	~		1
		Note: con		s may not be disc		Hand Brake	~		+
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	ofture	
						Tyres (lowest observed tread depth of tyres)			
							8.	-	mm
						Right front	8.		mm
						Left rear	4.	-	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	metinspectic	<u>on comments</u>			Suspension			·
2Wheel driv	/e.					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			·
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
curpets	Card					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		<u> </u>
Dashboa	iiu					Window winder FL	2		
- ·						Window winder FR	٢		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	2		
	-		•			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		1
						L			
Inspecte	d by: Rajesh Mayan					Date: 12 Feb 20	24		
I have read	and understood th	is condition c	juide. Name:			Signature:			