

Report ID: 25,572,858 Version: 3 22 Feb 2024 Created:

Make:	Nissan	Model:	Fairlady	Body Style:	Convertible		Pass	Fail	N/A	
Year:	2008	Registration:	MBK893	Reg Expiry:	26 Sep 2024	Engine	1	l	L	
WoF Expiry:		Odometer:	108,163 Kms	Good No:	25572858	Oil level	~			
VIN:	7AT0DH2PX18400398	Next Service:		Service History	V: No	Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		с I I			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechar	ical inspection prior to	purchase and the	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:	S	-0	ls		s	Radiator / Hoses (visual)	~			
S = scratch	STE	A CO		10c	To	Transmission	v			
D = dent					EID S	Operation	~			
R = rust				10		Noise	~			
PT = paint def C = crack	ect			+		Clutch	V			
P = pin dent	Ho	KI				CV joints			~	
* = decals	sc pp			AL-	ENPRIS	Wheel bearings	~			
SC = stone chips										
W = significant scuffs S W S P W						Brakes				
						Performance	~			
Body Ins	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front		.0	mm	
						Right front		.0	mm	
						Left rear	6.	.0	mm	
Conditions During Body Inspection: Dry							Right rear 5.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
<u>Under Ca</u>	image & Under Bor	inet inspectic	on comments			Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock absorbers							~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Daabbaa	Good					Wipers (front & rear)	~			
Dashboa	ira					Window winder FL	~			
	-					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL			~	
						Window winder RR			<	
						Rear view mirrors	<			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	3			
Road Conditions During Test Drive: Dry Central locking										
			•			Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Sione Mae Date: 13 Feb 2024										

I have read and understood this condition guide.

Name:

Signature: