

Report ID: 25,577,210 Version: 2 30 Apr 2024 Created:

						Create			1
Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N//
Year:	2014	Registration:	HSB662	Reg Expiry:	18 May 2024	Engine			
	23 Jan 2025	Odometer:	147,829 Kms	Good No:	25577210	Oil level	~		
/IN:	KL3CA26U9EB019101	Next Service:	154000	Service Histor	/: No	Smoke & fumes	~		
Nata Thiana						Performance	~		
This report is	port is not a warranty a guide only. Conside	eration is made	for age and mileage	ge. Parts have not	been dismantled or	Noise	<		
diagnostic te	sting undertaken. The lical inspection prior to	vehicle has beer	n driven up to 50km	/h from cold. The	/endor recommends	Cooling System			
a full mechai	ical inspection prior to	purchase and ti	lis can be arranged		narge.	Coolant condition	~		
	SC		SC W S D S		S SC W	Performance	~		
Key:				502	3501	Radiator / Hoses (visual)	~		
= scratch	AL				Tan	Transmission			4
0 = dent 1 = rust	sc w			210	S SC W	Operation	~		Τ
PT = paint def	ect NP	F I				Noise	~		+
C = crack				$+ \mathbf{\nabla}$	S SC W	Clutch			~
P = pin dent					741L	CV joints	~		+
= decals	sscw 916				S SC W	Wheel bearings	~		
SC = stone chi		20		Lar	¥ —	Brakes	•		
V = significan	t scuffs SC W	$- \emptyset$	S SC W S SC		S SC W	Performance	~		1
Dadulaa		Note: som	ne defects & blemish	les may not be disp	layed in the diagram	Hand Brake	~		
BODY INS	pection Comments	1				Tyres (lowest observed tread	d depth	of tyre	⊥ es)
						Left front	4.		mm
						Right front	4.		mm
						Left rear			mn
						Right rear	2.0 mm 2.0 mm		
Conditions During Body Inspection: Dry						Spare	Z.	0 Yes	
Under Ca	rriage & Under Bor	nnet Inspectio	on Comments			Suspension		res	
		•				Suspension performance	~		1
•						Steering performance	~		
						Shock absorbers	~		+
							V		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
	Average					Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		⊢
						Indicators	~		$\perp$
Panels	Average					Dashboard warning lights	~		$\downarrow$
Dashboa	Average					Wipers (front & rear)	~		
Dashbud						Window winder FL	~		
<u> </u>	_					Window winder FR	2		
	<u>Comments</u>					Window winder RL	<		
Drives okay	,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		$\square$
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		+
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			-
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
									<u> </u>
Inspecte	d by: Donovan Matar	-				Date: 21 Feb 20	24		

I have read and understood this condition guide.

Name: .....

Signature: .....