

Report ID: 25,578,481 Version: 2 Created: 22 Feb 2024

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	LUG681	<b>Reg Expiry:</b>	29 May 2024	Engine	1	I	
WoF Expiry:	11 Dec 2024	Odometer:	175,433 Kms	Good No:	25578481	Oil level	~		
VIN:	MPBUMFF60JX191856	Next Service:	180,200 km	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	or an additional o	narge.	Coolant condition	~		
			SC P SC		SC	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			1
R = rust	PT SC			210		Operation	~		
PT = paint def	ect NP				11111	Noise	~		
C = crack						Clutch			~
P = pin dent	P SC DE				74116	CV joints	~		
						Wheel bearings	V		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts SC SC DSC						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Grill emblem cracked front.						Tyres (lowest observed tread depth of tyres)			es)
Front bumper sensor moulding needs refit.						Left front	6	5	mm
Windscreer	chip out of cva.					Right front	e	5	mm
						Left rear	5	5	mm
Conditio	ns During Body Ins	pection:	Dry			Right rear	5	5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
4WD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments No key for rear tray lid.						Window winder RL	~		
	cai tiay ilu.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicm: Combelt						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
Inspected by: Imraan Bryant Date: 22 Feb 2024									
		_	_						

I have read and understood this condition guide.

Name: .....

Signature: .....