

Report ID: 25,588,235 Version: 4 20 Feb 2024 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	JYF887	Reg Expiry:	29 Jan 2024	Engine			
WoF Expiry:	28 Sep 2024	Odometer:	322,758 Kms	Good No:	25588235	Oil level	~		
VIN:	MMU148LK0GH64336	Next Service:	332,764 KMS	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	S D SC	-0	DPSC DPSC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	EIN S	Operation	~		
R = rust				$\int$	JHH	Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent						CV joints			~
* = decals	PSC PSC			AL.	EIP s	Wheel bearings	~		•
SC = stone chips						Brakes	v		
W = significant scuffs SC D SC D SC D SC D P SC						Performance			
Noto: como defecte & blemiches may not be displayed in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Play in fuel flap latch.						Tyres (lowest observed tread depth of tyres)			
					Left front	5.		mm	
					Right front	5.		mm	
r						Left rear	3.	.5	mm
Conditions During Body Inspection: Wet						5			mm
Under Corriges & Under Pennet Increation Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Correcto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Average s	teering wheel w	orn.			Wipers (front & rear)	~		
Dashboa	rd		-			Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 277,497						Reversing camera	~		-
L									
Inspected by: Troy Smith Date: 20 Feb 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....