

Report ID: 25,588,827 Version: 2 Created: 23 Feb 2024

Make:	Volkswagen	Model:	Crafter	Body Style:	Van		Pass	Fail	N/A
Year:	2018		LPA140	Reg Expiry:	15 Aug 2024	Engine			
WoF Expiry:		Odometer:	132,466 Kms	Good No:	25588827	Oil level	~		
VIN:	WV1ZZZSYZJ9045060			Service Histor		Smoke & fumes	~		
	WV122251255015000		149,410		. 110	Performance	~		
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition	~		
		_				Performance	~		
Key:	S D SC W	-0	SP SDRP	Mar	S D R P	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			X	Transmission	v		
D = dent	sscw			1n-	BID	Operation	~		1
R = rust				10		Noise	~		
PT = paint def C = crack	ect M			+	S D R	Clutch	~		
P = pin dent	Ho				JUII —	CV joints	v v		
* = decals	SRSC PR			AL-	ELIP SP	Wheel bearings	-		
SC = stone chips							~		
W = significant scuffs S SC S D P S D P W S D P W						Brakes			
		Nataraa				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	<ul> <li></li> </ul>		
Large Dent / Damage on Front Right Corner of Roof						Tyres (lowest observed tread depth of tyres)			
						Left front	4		mm
						Right front		.5	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry					Right rear	6	.0	mm	
Under Carriage & Under Pennet Inspection Comments						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil Seepage	2					Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Drivers Seat Torn						Electrical / Accessories			
Seats	Drivers Sea	atiom				Head lights	~		
Carpets	Average					Tail lights	~		
Carpets	-					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachhar	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL			~	
Spare Wheel Lowering Tool Missing Spare Wheel in Cargo Area						Window winder RR			~
Cargo Lift in						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		•
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
			•			Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		1
							1		
Inspecte	d by: Samuel Weir					Date: 22 Feb 20	24		
I have read	and understood th	is condition g	uide. Name:			Signature:			