

Basic Vehicle Condition Guide

Report ID: 25,589,542

Version: 3


21 Apr 2024 Created:

Pass Fail N/A

Make: Model: Ford Fiesta **Body Style:** Hatchback Year: 2010 Registration: PRZ278 Reg Expiry: 01 Apr 2024 **Odometer:** WoF Expiry: 13 Nov 2024 239,534 Kms **Good No:** 25589542 VIN: WF0JXXGAJJAJ45758 **Next Service:** Unknown Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Transmission leak

| Interior Comments | | | |
|-------------------|--------------------------------|--|--|
| Seats | Significant tears in rear seat | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Parcel tray missing

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Samuel Weir

Evidence of Cam Belt Replacement: No

Kms:

| Engine | | 1 | |
|------------------------------|--------------|---------|----------|
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | | ~ | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | v | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | • | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | \(\times \) | | |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 2 | .5 | mm |
| Right front | 3.0 | | mm |
| Left rear | | | mm |
| Right rear | 6.0 mm | | |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ļ | ļ | 1 |
| Operation | ~ | | |
| Electrical / Accessories | l | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | <i>v</i> | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | v | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | • | | |
| Remote locking | • | | |
| Sat. Nav. (basic test only) | | | ., |
| | | | ., |
| Reversing camera | ı | 1 | <i>V</i> |

I have read and understood this condition guide.

Name:

Signature:

23 Feb 2024