

Report ID: 25,590,551 Version: 1 27 Feb 2024 Created:

| Make: | Nissan | Model: | Tiida | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|---------------------------------|-----------------------|------------------------------|--------|---------|-----|
| Year: | 2010 | Registration: | KQA219 | Reg Expiry: | 06 Oct 2024 | Engine | | | · |
| WoF Expiry: | 24 Feb 2025 | Odometer: | 129,178 Kms | Good No: | 25590551 | Oil level | ~ | | |
| VIN: | 7AT0DH78X17401635 | Next Service: | 139000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Parts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | his can be arranged fo | r an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | S | -0 | S S | -161- | s | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | s sc | | | TIN | | Operation | ~ | | |
| R = rust PT = paint defe | | | | $\left[\right] \left[\right]$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | - | | ~ |
| P = pin dent | HID | | | | 거네 | CV joints | ~ | | - |
| * = decals | s 916 | | | - Jul | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significan | t scuffs S | | S P | | | Performance | ~ | | |
| Podylog | action Commonts | Note: son | ne defects & blemishes | may not be disp | played in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread | depth | of tyre | es) |
| | | | | | | | | | mm |
| | | | | | | Right front | 7. | 0 | mm |
| | | | | | | Left rear | 7. | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7.0 mm | | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock absorbers | | | | | | | ~ | | |
| Air Conditioning / Heater | | | | | | | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | / Telege | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | , Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry Central locking | | | | | | | | | |
| | | | | | | Remote locking | ~ | | |
| - | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspected by: Gary Adams Date: 22 Feb 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: