

## **Basic Vehicle Condition Guide**

Report ID: 25,590,956

Pass

1

Version:

Engine

Oil level

Smoke & fumes

Created: 07 Mar 2024


Fail

N/A

Make: Subaru Model: Legacy **Body Style:** Wagon Year: 2011 Registration: LFC37 **Reg Expiry:** 01 Dec 2024 WoF Expiry: **Odometer:** 07 Mar 2025 142,651 Kms **Good No:** 25590956 VIN: 7AT0GF0BX18064836 **Next Service:** 150186kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 97,000

Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 8.0 Right front 8.0 mm Left rear 8.0 mm Right rear 8.0  $\mathsf{mm}$ Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

Inspected by:	Darian Beyer-Way

22 Feb 2024

Date: