

Basic Vehicle Condition Guide

Report ID: 25,592,377


Version: 1

Created: 29 Feb 2024

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2008 Registration: MCP940 Reg Expiry: 20 Apr 2024 **WoF Expiry: Odometer: Good No:** 13 Mar 2025 84,262 Kms 25592377 VIN: 7AT0C139X19100219 **Next Service:** 95000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	has sticky dash		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Darian Beyer-Way Date: 22 Feb 2024

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front		7	mm	
Right front		7	mm	
Left rear	4.0		mm	
Right rear	4.0		mm	
Spare		Yes		
Suspension		ı		
Suspension performance	~			
Steering performance	\(\sigma \)			
Shock absorbers	'			
Air Conditioning / Heater		1	1	
Operation	•			
Electrical / Accessories				
Head lights	•			
Tail lights	•			
Indicators	\(\times \)			
Dashboard warning lights	•			
Wipers (front & rear)				
Window winder FL Window winder FR	\(\times \)			
Window winder FR Window winder RL	•			
Window winder RE Window winder RR	.,			
Rear view mirrors	<i>V</i>			
Radio (basic test only)	\(\triangle \)			
CD (basic test only) Number of keys				
Central locking	2			
Remote locking	1			
Sat. Nav. (basic test only)			-	
Reversing camera	V			
eversing curriera				

Signature: