

Report ID: 25,592,472


Version: 1

Created: 28 Feb 2024

| Make: | Mitsubishi | Model: | Outlander | Body Style: | Wagon |
|-------------|-------------------|---------------|-------------|-----------------|--------------|
| Year: | 2013 | Registration: | KUE434 | Reg Expiry: | 21 Feb 2025 |
| WoF Expiry: | 17 Jun 2024 | Odometer: | 179,807 Kms | Good No: | 25592472 |
| VIN: | 7AT0CJ3MX17008598 | Next Service: | 184000 | Service History | y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LH taillight cracked,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

| General | Comments |
|---------|----------|
| | |

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|--|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\times \) | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | l | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 4 | mm |
| Right front | | 4 | mm |
| Left rear | | 3 | mm |
| Right rear | | 3 | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | <u> </u> | 1 | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | | | |
| Indicators | \(\times \) | | |
| Dashboard warning lights | <i>\sqrt{\sq}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}</i> | | |
| Wipers (front & rear) | | | |
| Window winder FL | \(\triangle \) | | |
| Window winder FR | ~ | | |
| Window winder RL | <i>v</i> | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | |
| Number of keys | 2 | | |
| Central locking | 2 V | | |
| | | | |
| Remote locking | • | | |
| Sat. Nav. (basic test only) Reversing camera | ~ | | |
| neversing carriera | | | |
| Date: 39 Feb 30 | 24 | | |

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

Date: 28 Feb 2024