

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments 4wd

		Air Conditio	Air Conditioning / Heater		
		Operation	v		
Interior Comments		Electrical / A	Electrical / Accessories		
Seats	Average	Head light:	d lights 🖌		
Carpets	Average	Tail lights	~		
			v		
Panels	Average	Dashboard	warning lights 🖌		
	Average	Wipers (fro	nt & rear) 🖌 🖌		
Dashboard		Window w	inder FL 🖌		
General Comments		Window w	inder FR 🖌 🖌		
		Window w	inder RL 🖌		
		Window w	inder RR 🖌 🖌		
		Rear view r	mirrors 🖌		
		Radio (basi	c test only) 🖌		
		CD (basic t	est only)		~
		Number of	keys 1		
Road Conditions During Test Drive: Dry		Central loc	king 🖌		
			king 🖌		

Kms:

Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable

Inspected by: **Uriah Pepene**

14 Mar 2024 Date:

Sat. Nav. (basic test only)

Reversing camera

Right rear

Suspension

Suspension performance

Steering performance

Shock absorbers

Spare

I have read and understood this condition guide.

Name:

Signature:

~

Fail

N/A

V

mm

mm

mm

mm

4.5

V

V

~

Yes