

Report ID: 25,602,428 Version: 1 07 Apr 2024 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	KUC762	<b>Reg Expiry:</b>	19 Apr 2024	Engine			
WoF Expiry:	31 Mar 2024	Odometer:	146,163 Kms	Good No:	25602428	Oil level	~		
VIN:	7AT0DH78X17023335	Next Service:	156000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S SC S		S PT SC S SC	S	S SC	Performance	r		
Key:	330 13	-0	37130 330		330	Radiator / Hoses (visual)	r		
S = scratch D = dent R = rust PT = paint defect C = crack						Transmission			
						Operation		~	
						Noise	r		
						Clutch			~
P = pin dent						CV joints	r		
* = decals SSC 999 SSC						Wheel bearings	V		
SC = stone chips						Brakes	I		
W = significant scuffs S SC S SC S SC S W						Performance	~		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Front and rear bumper misaligned/									mm
						Right front	Right front 6		mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd/LH balljoint grease coming out/underbody surface rust in rear						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	I		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers bo	ttom pad ripped				Head lights	~		
	Average					Tail lights	r		
Carpets	Avelage					Indicators	r		
Panels	Average					Dashboard warning lights	r		
	glue stuck	on dash				Wipers (front & rear)	~		
Dashboa	rd	on dasti				Window winder FL	~		
						Window winder FR	r		
<u>General Comments</u>						Window winder RL	r		
Intermittent Gearbox shudder						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Uriah Pepene Date: 07 Apr 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....