

Report ID: 25,602,444 Version: 3 29 Feb 2024 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail	N/A
Year:	2004	Registration:	GDU593	Reg Expiry:	05 May 2024	Engine	I	I	1
WoF Expiry:		Odometer:	217,821 Kms	Good No:	25602444	Oil level	~		
VIN:	7AT08G7HX11202187	Next Service:	216,000 - Overdue	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		C 1 1			Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SRSC	-0	SP SP		s	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			X	Transmission	•		
D = dent	ssc 6/6			The	EI SP	Operation	~		
R = rust PT = paint def					JHIH	Noise	~		
C = crack				+	S	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals SRSC PIP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S PT S R P						Performance	~		
		Note: som	ne defects & blemishe	s may not be disn		Hand Brake	~		
	pection Comments		le délects à biemisne	s may not be disp	ayed in the diagram		-	oftur))
Rust bubbles under left rear window						Tyres (lowest observed tread depth of tyres)			
								.0	mm
						Right front		.0	mm
						Left rear			mm
Conditions During Body Inspection:						Right rear			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Front lower ball joints and tie rod ends bushings split						Suspension			
Oil leak	ball joints and the rou e	inus businings sp	iit			Suspension performance	<u> </u>	~	
						Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/ Weitage					Dashboard warning lights		~	
Dashboa	rd Average					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concret						Window winder FR	~		
General Comments Check engine light					Window winder RL	~			
Knocking noise from engine					Window winder RR	~			
Knocking noise from suspension Rear shock absorbers ineffective						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
En aliz - T'	ning Mashaulau	T:	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Samuel Weir Date: 29 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: