

Report ID: 25,602,588 Version: 1 07 Mar 2024 Created:

Make:	Mazda	Model:	Atenza	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2005	<b>Registration:</b>	LYW851	<b>Reg Expiry:</b>	24 Jul 2024	Engine	1			
WoF Expiry:	26 Apr 2024	Odometer:	182,434 Kms	Good No:	25602588	Oil level	~			
VIN:	7AT0C139X18400362	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:	s sc sc		S SC S SC	SC	W S D SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	sscw 616			The	S SC	Operation	~			
R = rust PT = paint defe				$\prod$	JHH	Noise	~			
C = crack					S PT SC	Clutch			~	
P = pin dent						CV joints	~		-	
* = decals	ssc 916			The	SDSC	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S SC SC W S SC S SC						Performance V				
		Natarcam				Hand Brake	v v			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftwa	) )	
					Tyres (lowest observed tread depth of tyres)   Left front 3					
								3	mm mm	
						Right front				
						Left rear		5.5		
Conditions During Body Inspection: Wet						Right rear	5.5		mm	
Under Carriage & Under Bonnet Inspection Comments						· · · · · · · · · · · · · · · · · · ·	Spare Yes			
No underbody inspection						Suspension				
	buy inspection					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	1			
Interior Comments						Operation		~		
marks wear						Electrical / Accessories				
Seats						Head lights	~			
Carpets	marks, we	ar				Tail lights	~			
						Indicators	~			
Panels	marks					Dashboard warning lights	~			
Dashboa	cracks, we	ar				Wipers (front & rear)	~			
						Window winder FL	~			
						Window winder FR	~			
General Comments Key fob broken doesn't work have to use key to unlock and lock and start car.					Window winder RL	~				
	iken übesnit work nave	to use key to unl	ock and lock and start	cdi.		Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Wet Central locking										
	-					Remote locking		~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
·										
Inspected by: Melissa Wilson Date: 07 Mar 2024										

I have read and understood this condition guide.

Name: .....

Signature: .....