

I have read and understood this condition guide.

Signature:

Make:	Holden	Model:	Equinox	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	Registration:	LWA686	Reg Expiry:	09 May 2024	Engine			
WoF Expiry:	10 Dec 2024	Odometer:	70,396 Kms	Good No:	25607054	Oil level		~	
VIN:	3G0AX7EVXKS515867	Next Service:	75,000 kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
			S D *			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust						Transmission			
						Operation	~		
PT = paint defe		F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	s 616					Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Incr		Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
								mm	
						Right front	4		mm
						Left rear	7		mm
Conditions During Body Inspection: Wet					Right rear	7 mm		mm	
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Fwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets	3000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
<u> </u>	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
L trans axle seal leaking,remote key not working x1.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 05 Mar 2024									

Name: