

Report ID: 25,607,134 Version: 1 14 Mar 2024 Created:

Signature:

Make: Mi	itsubishi	Model:	L300	Body Style:	Van		Pass	Fail	N/A
Year: 20)13	Registration:	QKT740	Reg Expiry:	06 Oct 2024	Engine	1		<u> </u>
WoF Expiry: 22	2 Sep 2024	Odometer:	142,270 Kms	Good No:	25607134	Oil level	~		
	IAHNP14VDA80074	Next Service:	145,000	Service Histor	y: No	Smoke & fumes	~		+
						Performance	~		
	r <mark>t is not a warranty</mark> guido oply. Conside	vation is made	for and milaan	Darte have not	been dismantled or	Noise	~		
diagnostic testin	ng undertaken. The v	ehicle has beer	driven up to 50km/h	n from cold. The '	Vendor recommends	Cooling System			
a full mechanical	l inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch	STE	A U			X	Transmission	•		
D = dent	ISSC 6/6			The		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defect C = crack				+		Clutch	~		
P = pin dent						CV joints	•		~
* = decals	ssc pp					Wheel bearings	~		
SC = stone chips	10	VA		1au		Brakes	V		
W = significant sci	uffs	- 0		JUF		Performance	~		
		Noto: com	le defects & blemishes		laved in the diagram				
Body Inspec	ction Comments	Note: son	le délects à biennisne	s may not be disp	nayed in the diagram	Hand Brake		. (
Body work average, has been a work van.						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	-	mm
						Right front	6.		mm
						Left rear	6.	-	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	age & Onder Bon	inet inspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			~
Interior Comments						Electrical / Accessories			
Seats	POOL					Head lights	~		
Carpets	Poor					Tail lights	~		
						Indicators	~		
Panels	Poor					Dashboard warning lights	~		
Dashboard	Poor					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	2		
General Con	<u>mments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		_
Road Condit	tions During Test	Drive:	Dry			Central locking			~
	-					Remote locking			~
						Sat. Nav. (basic test only)			~
	Cam Belt Replace	ement· V	es	Kms: 10)1,570		L		
Evidence of (cum ben neplace	cificiti. I	C3	1111 5 . 10	1,570	Reversing camera			~
	y: Gary Adams				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Date: 29 Feb 20			~

I have read and understood this condition guide.

Name: