

Report ID: 25,607,240 Version: 1 09 Mar 2024 Created:

Make:	Honda	Model:	Accord	Body Style:	Sedan		Pass	Fail	N/A
Year:	2009	Registration:	EUD188	Reg Expiry:	24 Sep 2024	Engine	1	L	I
WoF Expiry:		Odometer:	111,215 Kms	Good No:	25607240	Oil level	~		
VIN:	MRHCP36508P050256	Next Service:	114600	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	S SC W	-0	s sc sc			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S PT SC W			TIN	S SC	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent					741L	CV joints	~		•
* = decals	sc 916			- No	ELLA S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S SC S SC W S						Performance	~		
Dedulmen		Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed trea	d depth	of tyre	es)
Stone chips front window screen									mm
						Right front		.5	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear		5.2 mr	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	wear					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	scratches,	wear				Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd wear					Window winder FL	~		
	1				J	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		I
Road Conditions During Test Drive: Dry						Central locking	~		
			Dry			Remote locking	~		
Engine Tir	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Yes Kms: 78,211						Reversing camera	~		
	-						-		
Inspected by: Melissa Wilson Date: 09 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: