

Report ID: 25,608,331 Version: 2 07 Mar 2024 Created:

Signature: .....

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2008	<b>Registration:</b>	MBP506	Reg Expiry:	13 Nov 2024	Engine	1		1	
WoF Expiry:	20 Mar 2025	Odometer:	59,413 Kms	Good No:	25608331	Oil level	~			
VIN:	WVWZZZ1KZ8U01053	Next Service:	74413	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
	SC		SC SC	SW	SC	Performance	~			
Key:	Bell	-0				Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	S PT SC W			210	HIL PT W	Operation	~			
PT = paint defe	ect NP				70111	Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	sc w dR				24114	CV joints	~			
* = decals				10	P SC	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
w – significan	SC SV	N	PT P SC W S P		SC W	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Both rear wheel centre badges missing						Tyres (lowest observed tread	d depth	of tyre	2S)	
Small chips front screen						Left front	4.1 mm		mm	
Scuffing front bumper lip & clear coat peel clear coat peel rear bumper, LF door bump strip						Right front	4.4		mm	
	,,,	F F				Left rear	5.	4	mm	
Conditions During Body Inspection: Dry						Right rear	5.5 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
All ok						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Comoto	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	fabric trim	loose on all pan	els, average			Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u>					Window winder RL	~				
Vehicle dro	ve very well.					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry Central locking							~			
	-	<b></b>	•			Remote locking	~			
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Mike Greenfield Date: 07 Mar 2024									

I have read and understood this condition guide.

Name: .....