

Basic Vehicle Condition Guide

Report ID: 25,609,465


Version: 3

Created: 22 Mar 2024

Make: Model: **Body Style:** Holden Colorado Utility Year: 2018 Registration: LNW502 Reg Expiry: 31 Jul 2024 WoF Expiry: **Odometer: Good No:** 13 Mar 2025 255,434 Kms 25609465 VIN: MMU148EK0KH61104 **Next Service:** 266,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Small tear drivers, others good		
Carpets	Average		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Gary Adams Inspected by:

Create	d: 22	2 Mar 2	024		
	Pass	Fail	N/A		
Engine			l		
Oil level	~				
Smoke & fumes	\(\times \)				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	V				
Performance	<i>y</i>				
Radiator / Hoses (visual)	\(\triangle \)				
Transmission					
Operation	V				
Noise	<i>y</i>				
Clutch			•/		
CV joints			1/		
Wheel bearings	~				
Brakes	<i>V</i>				
Performance					
Hand Brake					
Tyres (lowest observed tread	denth	of tyre)c)		
Left front	I		mm		
Right front	3.0		-		
Left rear	3.0		mm		
	2.0		mm		
Right rear	2.0		mm		
Spare Yes					
Suspension					
Suspension performance Steering performance	•				
	V				
Shock absorbers	•				
Air Conditioning / Heater			I		
Operation	•				
Electrical / Accessories					
Head lights	-				
Tail lights	~				
Indicators	\(\triangle \)				
Dashboard warning lights					
Minore (front 0 re)	•/				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FL Window winder FR	~				
Window winder FL	\(\sigma \)				
Window winder FL Window winder FR	~				
Window winder FL Window winder FR Window winder RL	\(\sigma \)				
Window winder FL Window winder FR Window winder RL Window winder RR	\(\sigma \)				
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors	\(\times \) \(\t		<i>V</i>		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	\(\times \) \(\t		V		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	V V V V		V		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	V V V V		~		
Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	V V V V		V		

04 Mar 2024

Date:

I have your dance on a consideration and their considerations arrived a	Mama a.	Ciamatura
I have read and understood this condition guide.	Name:	signature: