

Basic Vehicle Condition Guide

Report ID: 25,611,705


Version: 2

Created: 01 Mar 2024

Make: Model: ZS MG **Body Style:** SUV Year: 2020 Registration: NBG513 Reg Expiry: 29 Sep 2024 WoF Expiry: **Odometer: Good No:** 30 Sep 2024 38,543 Kms 25611705 VIN: LSJW74C9XLZ128493 **Next Service:** 39500 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front window screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

| Interior Comments | | | | |
|-------------------|-------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | marks | | | |
| Dashboard | Good | | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Melissa Wilson 01 Mar 2024 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | | |
|--|---|------|-----|--|--|--|
| Engine | | | | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | <i>v</i> | | | | | |
| Performance | ~ | | | | | |
| Noise | ~ | | | | | |
| Cooling System | | | | | | |
| Coolant condition | ~ | | | | | |
| Performance | \(\triangle \) | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | ~ | | | | | |
| Clutch | | | ~ | | | |
| CV joints | ~ | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | | | | | |
| Performance | ~ | | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | |
| Left front | 4 | .5 | mm | | | |
| Right front | 4.5 | | mm | | | |
| Left rear | : | 5 | mm | | | |
| Right rear | 5.6 | | mm | | | |
| Spare | | Yes | | | | |
| Suspension | • | | | | | |
| Suspension performance | ~ | | | | | |
| Steering performance | ~ | | | | | |
| Shock absorbers | ~ | | | | | |
| Air Conditioning / Heater | | | | | | |
| Operation | ~ | | | | | |
| Electrical / Accessories | • | • | | | | |
| Head lights | ~ | | | | | |
| Tail lights | ~ | | | | | |
| Indicators | ~ | | | | | |
| Dashboard warning lights | VVV | | | | | |
| Wipers (front & rear) | ~ | | | | | |
| Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | V | | | | | |
| Window winder RR | ~ | | | | | |
| Rear view mirrors | ~ | | | | | |
| Radio (basic test only) | ~ | | | | | |
| CD (basic test only) | | | ~ | | | |
| Number of keys | 2 | | | | | |
| Central locking | ~ | | | | | |
| Remote locking | ~ | | | | | |
| Sat. Nav. (basic test only) | ~ | | | | | |
| Reversing camera | ~ | | | | | |
| | | - | - | | | |

Signature: