

Report ID: 25,615,973 Version: 3 16 Apr 2024 Created:

Make:	Nissan	Model:	Bluebird	Body Style: Sedan		Pass	Fail	N/A
Year:	2013	Registration:	-	Reg Expiry:	Engine	-		L
WoF Expiry:		Odometer:	99,705 Kms	Good No: 25615973	Oil level	~		
VIN:	7AT0DH1EX24008127			Service History: No	Smoke & fumes	~		
				,	Performance	~		
	port is not a warranty		<i>.</i>		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends					Cooling System			
a full mechan	ical inspection prior to	Coolant condition						
					Performance	~		
Key:		-0			Radiator / Hoses (visual)	~		
S = scratch					Transmission			
					Operation V			<u> </u>
R = rust					Noise	~		
PT = paint defe C = crack	ect M				Clutch	V		
P = pin dent	Ho	KI						~
* = decals	- MIC				CV joints	~		
SC = stone chips					Wheel bearings	Wheel bearings		
W = significant scuffs								<u> </u>
		N			Performance	~		
Body Insp	pection Comments	Note: son	he defects & biemisnes	s may not be displayed in the diagram	Hand Brake		<u> </u>	Ļ
					Tyres (lowest observed tread depth of tyres)			-
					Left front	6.	-	mm
					Right front	6.	0	mm
					Left rear	5.	0	mm
Conditions During Body Inspection: Dry					Right rear	5.0 m		mm
					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
FWD					Suspension performance	~		
					Steering performance	~		
		Shock absorbers	~					
					Air Conditioning / Heater			
Interior Comments					Operation 🖌			
<u>interior</u> C		Electrical / Accessories						
Seats	Good				Head lights	~		
Carpets	Good				Tail lights	~		
Carpets					Indicators	~		
Panels	Good				Dashboard warning lights	~		
	, Good				Wipers (front & rear)	~		
Dashboa	ru				Window winder FL	~		
	_				Window winder FR	~	_	
General Comments					Window winder RL	~		
					Window winder RR	~		
					Rear view mirrors	~		
					Radio (basic test only)	~		
		CD (basic test only)			~			
		Number of keys	1					
Road Conditions During Test Drive: Dry Central locking								
Remote locking								
-	ming Mechanism:	Timing	Chain		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	Reversing camera	~					
Inspected by: Marlon Espena Date: 10 Apr 2024								

I have read and understood this condition guide.

Name:

Signature: