

## **Basic Vehicle Condition Guide**

Report ID: 25,615,987


Version: 2

Created: 04 Apr 2024

Make: Model: Toyota Aqua **Body Style:** Hatchback Year: 2013 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 22 Mar 2025 72,801 Kms 25615987 VIN: 7AT0H65YX24147318 **Next Service:** 82799km Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

FWD.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Todd Cullum Date: 04 Apr 2024

Create	u: 0 <sup>2</sup>	4 Apr 2	.024
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission	ı		1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front			mm
Right front	7		mm
Left rear		3	mm
Right rear	8		mm
Spare	· ·	Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	V		
Tail lights	<i>y</i>		
Indicators	~		
Dashboard warning lights	<i>y</i>		
Wipers (front & rear)	\( \times \) \( \t		
Window winder FL	<i>y</i>		
Window winder FR	<i>y</i>		
Window winder RL	·		
Window winder RR	\( \times \)		
Rear view mirrors	~		
Radio (basic test only)			
CD (basic test only)	\( \sigma \)		
Number of keys	2		<u> </u>
Central locking	•		
Remote locking	•		
			.,
Sat. Nav. (basic test only)  Reversing camera	.,		
neversing currera			
Date: 04 Apr 201	24		

I have read and understood this condition guide.

Name: .....

Signature: .....