

Report ID: 25,618,335 Version: 1 19 Mar 2024 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2006	Registration:	KSU820	Reg Expiry:	24 May 2024	Engine				
WoF Expiry:	08 Jun 2024	Odometer:	64,632 Kms	Good No:	25618335	Oil level	~			
VIN:	WVWZZZ1KZ6U02679	Next Service:	75158	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~			
						Performance	~			
Key:	L	-0	PT PT	$\overline{\mathbf{a}}$		Radiator / Hoses (visual)	~			
S = scratch						Transmission			·	
D = dent R = rust	- HA			715	HIL	Operation	~			
PT = paint defe				$\left[ \left( \right) \right]$		Noise	~			
C = crack						Clutch	~			
P = pin dent	HID				74116	CV joints	~			
* = decals	MA			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significant	scuns S			S		Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
	bection comments					Tyres (lowest observed trea	d depth	of tyre	es)	
						Left front		1	mm	
						Right front	4	1	mm	
						Left rear	4	1	mm	
Condition	ns During Body Ins	pection:	Dry			Right rear	4	1	mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Correcto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dachhar	rd Good					Wipers (front & rear)	~			
Dashboa	iu					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Con	ditions During Test	Drive:	Dry			Central locking	~			
Enging Ti	ning Machanism	Timine	Chain			Remote locking	~			
Engine Timing Mechanism: Timing Chain   Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)	~			
Evidence	or Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~	
Inspected	Inspected by: Skyone Auto LTD Date: 19 Mar 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....