

Report ID: 25,627,717 Version: 1 14 Mar 2024 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006		JCY392	Reg Expiry:	17 Sep 2024	Engine	1 435	1 011	
WoF Expiry:		Odometer:	133,327 Kms	Good No:	17 Sep 2024 25627717	Oil level	~		
									─
VIN:	WVWZZZ1KZ6U01309	Next Service:	139,800kms	Service Histor	y: No	Smoke & fumes	~		—
Note: This report is not a warranty						Performance	~		<u> </u>
This report is	a guide only. Conside					Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
			J		J	Coolant condition	~		
Kow	S SC)	SD SDPT		S	Performance	~		
Key: S = scratch		\sim (0)		5(0)7		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s sc			10	HILLS	Operation	~		
PT = paint def	ect NP				111/1	Noise	~		
C = crack					S R SC	Clutch			V
P = pin dent	HID				74114	CV joints		~	
* = decals	ssc 916			- No		Wheel bearings	~	-	
SC = stone chips						Brakes			<u> </u>
W = significant scuffs PT SC W S						Performance			
						Hand Brake			
Body Inspection Comments									
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0 mm		
						Right front	1	.4	mm
						Left rear	2.0		mm
Conditions During Body Inspection: Dry						Right rear	3	.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Leaking fro	m left front CV. Minor w	eep				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		1
						Air Conditioning / Heater			1
						Operation		~	1
Interior Comments						Electrical / Accessories	I	-	1
Seats	Good					Head lights	~		
Jeats						Tail lights	~		+
Carpets	Good								
Deve 1	Poor						~		
Panels						Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Right side of Centre Aircon vent is broken. Cloth of interior trims are sagging. Left rear door can not unlock by remote or central rocking.						Window winder RR	~		
			2			Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	1		J
Road Con	ditions During Test	Drive [.]	Dry]	Central locking		~	1
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	<u> </u>		~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 91	,961	Reversing camera			~
-									
Inspected by: Yuki Itohara Da							24		
I have read	and understood th	is condition o	juide. Name:			Signature:			