

Report ID: 25,630,221 Version: 1 15 Mar 2024 Created:

| Make: | Nissan | Model: | Serena | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|--------------------|------------------------|---------------------------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2008 | Registration: | MDM847 | Reg Expiry: | 05 Nov 2024 | Engine | | | |
| WoF Expiry: | 20 Mar 2025 | Odometer: | 171,900 Kms | Good No: | 25630221 | Oil level | V | | |
| VIN: | 7AT0DH3FX19166278 | Next Service: | 174100 | Service Histor | y: No | Smoke & fumes | V | | |
| | | | | | | Performance | r | | |
| | port is not a warranty | aration is made | for ago and miloago | Parts have not | been dismonthed or | Noise | V | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | nis can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | LS | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | SC DI | | | 715 | HIL | Operation | ~ | | |
| PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | + | | Clutch | | | ~ |
| P = pin dent | HID | | | | 게 | CV joints | ~ | | |
| * = decals | sc 916 | | | -No- | | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significan | t scuffs | $\neg \varnothing$ | \square | | S | Performance | ~ | | |
| Dedular | | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body insp | pection Comments | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| | | | | | | | | mm | |
| | | | | | | Right front | 6 | | mm |
| | | | | | | Left rear | 7 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7.0 mm | | |
| Conditions During Body Inspection: Dry | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | - | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Card | | | | | Tail lights | ~ | | |
| Carpets | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Navigation is Japan only. | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | I |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | | | |
| Rodu Con | unions During Test | Dive: | Dry | | | Remote locking | ~ | | |
| Engine Ti | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | - | | ~ |
| - | of Cam Belt Replac | _ | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | - | | | | | | - | 1 | |
| Inspected by: Reuben Harvey Date: 13 Mar 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: