

Basic Vehicle Condition Guide

Report ID: 25,634,109

Pass

1

~

Version: 3

Engine

Oil level

Smoke & fumes

Performance

Created: 12 Apr 2024


Fail

N/A

Make: Hyundai Model: Santa FE **Body Style:** SUV Year: 2016 Registration: JRP636 **Reg Expiry:** 16 Mar 2024 **WoF Expiry: Odometer:** 19 Apr 2025 174,508 Kms **Good No:** 25634109 VIN: KMHSU81XSGU61118 Next Service: 184000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Drives okay,

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 3.0 Right front 3.0 mm Left rear 3.0 mm Right rear 3.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 2 Central locking Remote locking Sat. Nav. (basic test only) Reversing camera

I have read and understood this condition guide.

Donovan Matara

ame.	

Signature:

15 Mar 2024

Date: