

Report ID: 25,635,432 Version: 2 08 May 2024 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A	
Year:	2013	Registration:	GTF89	Reg Expiry:	23 Jul 2024	Engine				
WoF Expiry:	30 Apr 2025	Odometer:	315,286 Kms	Good No:	25635432	Oil level	~			
VIN:	KMHSH81XSCU91935	Next Service:		Service Histor	V: No	Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		с I II	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
						Performance	~			
Key:	s sc w	-0	L SC		SC W	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	sw 6/6			The	S SC W	Operation	~			
R = rust				10	THIA	Noise	~			
PT = paint def C = crack				+	SC W	Clutch			~	
P = pin dent						CV joints	~			
* = decals	PSCW PSCW				SSC W	Wheel bearings	~			
SC = stone chi	ps US	20		JAL)	& <u> </u>	Brakes	V			
W = significant scuffs S D W P SC W P SC W P SC W						Performance				
		Note: con	ne defects & blemishes	may not be disp		Hand Brake	マ マ			
Body Insp	pection Comments	1016.301	le delects & blemsnes	s may not be disp	layed in the diagram		•	ofture		
						Tyres (lowest observed tread depth of tyres)				
						Left front	2.		mm	
						Right front	3.		mm	
						Left rear	510		mm	
Conditions During Body Inspection: Dry						Right rear	5.0		mm	
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes				
		meenspeede				Suspension			1	
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation				
Average						Electrical / Accessories				
Seats	Avelage					Head lights	~			
Carpets	Average					Tail lights	~			
	A					Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	Average					Wipers (front & rear)	~			
						Window winder FL	~			
						Window winder FR	~			
<u>General Comments</u> Drives okay ,					Window winder RL	~				
Drives okay	,					Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Donovan Matara Date: 21 Mar 2024										

I have read and understood this condition guide.

Name:

Signature: