

Report ID: 25,635,568 Version: 3 22 Mar 2024 Created:

Make:	Holden	Model:	Colorado 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2015	Registration:	JKL164	Reg Expiry:	21 Apr 2024	Engine	I		I
WoF Expiry:		Odometer:	225,005 Kms	Good No:	25635568	Oil level	~		
VIN:	MMU156MK0GH6162	Next Service:	235000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	S		S S		S	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust SSC SSC SSC SSC SSC SSC SSC SSC SSC SS						Operation	~		
PT = paint defect						Noise	~		
C = crack					S	Clutch			~
P = pin dent	ssc dk				~HILLS	CV joints	<		
* = decals SC = stone chips S						Wheel bearings	<		
W = significant scuffs						Brakes			
	S SC		S D SC S		S D	Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Moisture in lh tail light						Tyres (lowest observed tread depth of tyres)			
						Left front	8	3	mm
						Right front	8	3	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Wet						Right rear	8 mr		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Runs on die	esel fuel					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
drivers split						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (<u>Comments</u>					Window winder FR	~		
						Window winder RL	v		
						Window winder RR	v		
						Rear view mirrors	v		
						Radio (basic test only) CD (basic test only)	~		
						Number of keys	3		~
						Central locking			
Road Conditions During Test Drive: Wet						Remote locking	v		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			マ マ
	- F	•							•
Inspected by: Gary Adams Date: 15 Mar 2024									

I have read and understood this condition guide.

Name:

Signature: