

Report ID: 25,636,049 Version: 2 20 Mar 2024 Created:

Make:	Volkswagen	Model:	Tiguan	Body Style:	SUV		Pass	Fail	N/A	
Year:	2009	Registration:	FEP683	Reg Expiry:	29 Nov 2024	Engine				
WoF Expiry:	07 Sep 2024	Odometer:	119,777 Kms	Good No:	25636049	Oil level	~			
VIN:	WVGZZZ5NZAW0358	Next Service:	130000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		6			Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
		_				Performance	~			
Key:	S	-0	SP P			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation 🖌				
R = rust					THIA	Noise	~			
PT = paint def C = crack			-	+		Clutch	•		~	
P = pin dent	Ho					CV joints	~			
* = decals SC PP						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S P S						Performance				
		Nataraa					~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake				
						Tyres (lowest observed tread depth of tyres)				
						Left front	3.	0	mm	
						Right front	3.	0	mm	
						Left rear	5.0		mm	
Conditions During Body Inspection: Dry						Right rear	5.0 n		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare				
Under Ca	irriage & Under Bor	inet inspectio	on Comments			Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	<			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	ird					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
Reverse camera low quality						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2		L	
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~			
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		-	
L			-			<u> </u>	1		<u> </u>	
Inspected by: Gary Adams Date: 15 Mar 2024										

I have read and understood this condition guide.

Name:

Signature: