

Report ID: 25,641,379 Version: 1 20 Mar 2024 Created:

| Make: | Mitsubishi | Model: | Galant | Body Style: | Sedan | | Pass | Fail | N/A |
|--|------------------------|---------------|------------------------|------------------|--|---------------------------|------|--------|----------|
| Year: | 1996 | Registration: | AMD131 | Reg Expiry: | 05 Aug 2024 | Engine | | | L |
| WoF Expiry: | | Odometer: | 116,297 Kms | Good No: | 25641379 | Oil level | ~ | | |
| VIN: | 7A8CJ0J0702001725 | Next Service: | | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | , | Performance | ~ | | |
| | port is not a warranty | | с I II | | 1 IV | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | | | |
| | | | | | | Performance | ~ | | |
| Key: | SD | -0 | LIS | | S D | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | | | Operation | ~ | | |
| R = rust PT = paint defe | | | | \int | JHIH | Noise | ~ | | |
| C = crack | | | | | | Clutch | ~ | | |
| P = pin dent | Ho | | | | | CV joints | ~ | | |
| * = decals | sc 916 | | | AL. | EIIP I | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | <u> </u> |
| W = significant scuffs W S C C W | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishes | | laved in the diagram | Hand Brake | ~ | | |
| Body Insp | pection Comments | | | indy not be disp | | | - | oftyre |)) |
| | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| | | | | | | Left front | | 5 | mm |
| | | | | | | Right front | | 6 mm | |
| | | | | | Left rear | | | mm | |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 5 mm | | mm |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| 4Wheel drive. | | | | | | Suspension | | | |
| Engine gil, TM gil seepage | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock absorbers | | | | | | | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Average | | | | | | Electrical / Accessories | | | <u> </u> |
| Seats | | | | | | Head lights | ~ | | <u> </u> |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | / verage | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | ~ | | <u> </u> |
| | | | | | | Window winder FL | ~ | | <u> </u> |
| Ganaral | Comments | | | | | Window winder FR | ~ | | <u> </u> |
| | | | | | | Window winder RL | ~ | | <u> </u> |
| | | | | | | Window winder RR | ~ | | <u> </u> |
| | | | | | | Rear view mirrors | ~ | | <u> </u> |
| | | | | | | Radio (basic test only) | | ~ | <u> </u> |
| | | | | | | CD (basic test only) | | ~ | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Tes | t Drive: | Dry | | | Central locking | ~ | | |
| Engine Ti | ning Machanism | Cambel | - | | | Remote locking | ~ | | |
| Sat. Nav. (Dasic test Only) | | | | | | | | | ~ |
| Evidence | or Cam Beit Replac | ement: Y | es | Kms: 10 | 6,000 | Reversing camera | | | ~ |
| Inspected by: Rajesh Mayan Date: 20 Mar 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: