

Basic Vehicle Condition Guide

Report ID: 25,642,840


Version: 1

Created: 26 Mar 2024

Make: Model: Toyota Hiace **Body Style:** Van Year: 2005 Registration: CZY936 **Reg Expiry:** 02 Dec 2024 WoF Expiry: **Odometer:** 11 Jan 2025 100,488 Kms **Good No:** 25642840 VIN: JTFHX02P900005455 Next Service: 114500km Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Centre seat cup holder missing. L/F, Centre Front, R/F seatbelts frayed.

Tints damage. Dash air vent damage. Stone chip windscreen.

Missing interior tail gate trim. Missing floor edge trims. Tail gate seal damaged.

Rust on edge of tail gate floor. Holes in cargo painted floor. Headliner damage.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear wheel drive.

Rear tyres perishing. Rear tyres edge quicker wear.

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Average			
Dashboard	Good			

General Comments

Vehicle has no AC installed. 1x key remote not working. R/F step plate paint worn. Right tail light lens crack. Hot 64c.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Henry Manders

Create	d: 26	5 Mar 2	2024
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			1
Coolant condition	~		
Performance	<i>v</i>		
Radiator / Hoses (visual)	~		
Transmission	1		1
Operation	~		
Noise	~		
Clutch	<i>v</i>		
CV joints			~
Wheel bearings	~		
Brakes	<u> </u>		1
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	 es)
Left front		0	mm
Right front	1	0	mm
Left rear	4		mm
Right rear	4		mm
Spare	Yes		
Suspension	<u> </u>		
Suspension performance	~		
Steering performance	~		
Shock absorbers	\(\triangle \)		
Air Conditioning / Heater	l		ı
Operation			V
Electrical / Accessories	<u> </u>		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v v		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			V
Window winder RR			V
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		I
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)	-		V
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
neversing carriera			

I have read and understood this condition guide.

Name			

Signature:

26 Mar 2024

Date: