


<b>Make:</b>	Subaru	<b>Model:</b>	Impreza	<b>Body Style:</b>	Hatchback
<b>Year:</b>	2007	<b>Registration:</b>	PEP333	<b>Reg Expiry:</b>	24 May 2024
<b>WoF Expiry:</b>	27 Mar 2025	<b>Odometer:</b>	174,526 Kms	<b>Good No:</b>	25643056
<b>VIN:</b>	7AT0GF09X22003943	<b>Next Service:</b>	185,000	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Front bumper loose. Bullseye stone chip lower lhs

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Vehicle has belly pans that are held in place with cable ties. Rhf inner wheel guard cut in half. Front bumper under trim missing. Front tow eye cover missing. Runs on 95/98 octane fuel

**Interior Comments**

Seats	drivers material crack
Carpets	Average
Panels	scuffs scratches marks
Dashboard	Average

**General Comments**

Air conditioning and heating work fine at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 171,800

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.0	mm	
Right front	6.0	mm	
Left rear	6.0	mm	
Right rear	6.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Gary Adams

Date: 19 Mar 2024

I have read and understood this condition guide.

Name: .....

Signature: .....