


<b>Make:</b>	Mitsubishi	<b>Model:</b>	ASX	<b>Body Style:</b>	SUV
<b>Year:</b>	2013	<b>Registration:</b>	HCK819	<b>Reg Expiry:</b>	28 Oct 2023
<b>WoF Expiry:</b>	21 Jul 2024	<b>Odometer:</b>	230,739 Kms	<b>Good No:</b>	25643087
<b>VIN:</b>	JMFXLGA8WEZ00049;	<b>Next Service:</b>	232000	<b>Service History:</b>	Yes

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

**Body Inspection Comments**

Small chips front screen  
LH roof rail repaired at front end cap

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Outer edge wear both LH tyres

All else ok

**Interior Comments**

Seats	driver seat base upholstery damaged, otherwise ok
Carpets	hole in driver footwell area, average
Panels	Average
Dashboard	buttons missing RHS dash, otherwise average

**General Comments**

Vehicle drove well

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4	mm	
Right front	3.4	mm	
Left rear	3	mm	
Right rear	3.4	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Rea Symons

Date: 22 Mar 2024

I have read and understood this condition guide. Name: ..... Signature: .....