

Report ID: 25,644,110 Version: 2 Created: 21 Mar 2024

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	2005	Registration:	GGG394	Reg Expiry:	26 Mar 2024	Engine			
WoF Expiry:	08 Sep 2024	Odometer:	185,711 Kms	Good No:	25644110	Oil level	~		
VIN:	7AT0GF0BX11046543	Next Service:	195,500 KMS	Service Histor	y: No	Smoke & fumes	~		
AL						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	narge.	Coolant condition	~		1
	SC S		SC SC	S	SC	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	s sc w			710	S PT SC W	Operation	~		1
PT = paint defe	ect NP	r I		$\left(\left \left(\right) \right\rangle \right)$		Noise	r		
C = crack					SC	Clutch			~
P = pin dent	HIG				7414	CV joints	~		+
* = decals	sc 916			TO	ADP P	Wheel bearings	~		+
SC = stone chips						Brakes			1
W = significant scuffs SC S P SC P SC S SC						Performance 🖌			
Dealer	a crian Comment	Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	•	of tvre	L es)
						Left front		4.5 mm	
						Right front		.5	mm
						Left rear		.5	mm
Conditions During Body Inspection:						Right rear	6.0		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments Grease around RH cv boot.						Suspension			
						Suspension performance		~	
						Steering performance	~	•	
						Shock absorbers	~		
						Air Conditioning / Heater	•		<u> </u>
						Operation	~		1
Interior Comments						Electrical / Accessories	•		
Seats	Poor					Head lights	~		1
Seats						Tail lights	~		
Carpets	Good						~		
Panels	Average					Dashboard warning lights	<i>v</i> <i>v</i>		
Panels						Wipers (front & rear)	<i>v</i> <i>v</i>		<u> </u>
Dashboa	ard Average					Window winder FL			
						Window winder FL	v		+
General (Comments					Window winder FR Window winder RL	v		
Wheel brace missing.						v		+	
Slight noise from power steering pump					Window winder RR	v		+	
Suspension knock.					Rear view mirrors	V			
NOTE: Cambelt is next due for replacement at 200,000kms.						Radio (basic test only)	~		
						CD (basic test only)	~		<u> </u>
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Cambelt						Remote locking	~		──
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Lindence	or cam beit nepide		NU	11113.		Reversing camera			~
Inspected by: Caleb Spicer Lee						Date: 18 Mar 20	24		
	and understood th		uide Name			Signature			

and understood this conditio

Signature.