

Basic Vehicle Condition Guide

Report ID: 25,644,621

Pass

1

V

/

1

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Poversing camera

Sat. Nav. (basic test only)

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

20 Mar 2024 Created:

Fail

N/A

1

mm

mm

mm

 mm

4

5.5

5.5

1

/

/

1

2

1


~

Yes

Make: Holden Model: Barina **Body Style:** Hatchback Year: 2017 Registration: QGE672 **Reg Expiry:** 13 Jun 2024 WoF Expiry: **Odometer:** 05 Jan 2025 82,910 Kms **Good No:** 25644621 VIN: KL3TA48E9HB133014 **Next Service:** 92000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comm	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

Canaral	Commonts
Generai	Comments

Inspected by:

Drives well

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Jaykib Collins

I have read and understood this condition guide.

Kms:

	Neversing camera	_
	•	
	Date: 20 Mar 2024	
Name	Signature	
Name.	Signatura	